Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-WEYRAUCH B- 154-93-3031H-11

Field Name: ROBINSON LAKE Well File #: 29730

Date Incident:5/1/2015Time Incident:12:00Facility ID Number:County:MOUNTRAILTwp: 154Rng: 93Sec: 19Qtr:

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 0.2 Barrels 0.2 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

The fire was extinguished immediately upon discovery. There were no injuries or evacuations as a result of the fire.

Areal Extent:

N/A - the fire occurred on the well location.

Potential Environmental Impacts:

No impacts were observed following the fire.

Action Taken or Planned:

The fire was extinguished immediately upon discovery.

Wastes Disposal Location: There were no waste streams associated with this incident.

Agencies Involved:

Updates

Date: 5/4/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this incident remained on location. NDIC retains oversight.